HÄSSLEHOLM MILJÖ AB VI BRINNER FÖR EN HÅLLBAR FRAMTID	Appendix G: Specific requirements for Pumping Stations and Infiltrations		
Issued by The safety committee	Approved by/manager Sven Carlsson	Date 2020-12-01	Edition 01

Appendix G Specific requirements for Pumping Station and Infiltrations

General

- At study visits, the supervisor will provide vest
- Photographing and filming at the facility is only permitted after permission from responsible visitor attendant.
- Smoking is permitted only at unpaid breaks and outside fenced area.
- Signs, guardrails and obstructions shall be observed and followed.

Personal protective equipment

- Safety shoes shall always be used during work.
- Safety helmet shall be used during plumbing work, blasting work, crane work and work performed at level differences.
- Safety goggles shall be used during:
 - Cutting work
 - Usage, preparation and handling of chemicals that pose a risk for the eyes
 - Vegetation clearing
- Visitors/contractors shall follow given instructions regarding usage of personal protective equipment

Specific areas

 So-called hot works occur at the facility. This requires permission and only permit managers can issue these.

HÄSSLEHOLM MILJÖ AB VI BRINNER FÖR EN HÄLLBAR FRAMTID	Appendix G: Specific requirements for Pumping Stations and Infiltrations		
Issued by The safety committee	Approved by/manager Sven Carlsson	Date 2020-12-01	Edition 01

I have read and understood the meaning of above:				
Name (text) and company				
Date and signature				

Signed part of document is saved by HMAB